DEPARTMENT OF LABOR
www.dol.ks.gov

AMUSEMENT RIDE COMPLIANCE REVIEW

Warning - First Violation

K-ISH 516 (Rev. 6-17)

☑ Temporary Ride ☐ Permanent Ride ☐ Non-profit/Municipality

Inspection date: 8/16/2017 Name of KDOL auditor: Kyle Lang

Ride owner: Kelley's Cowboy Beetle Ride location: Coffeyville, KS

Number of rides: 2

Contact person: Johnna Kelley Phone: 918-915-0047 Email: JohnnaKelley@yahoo.com

YES	NO	
☐	☑	1. Valid permit and inspection decal affixed to each ride;
☑	☐	2. The current certification of an inspector's qualifications to inspect amusement rides;
☑	☐	3. The current certificate of inspection for each ride signed by a qualified instructor;
☑	☐	4. Daily maintenance and inspection records for each ride;
☑	☐	5. The amusement ride manufacturer's operational manual for each ride;
☑	☐	6. The amusement ride manufacturer's nondestructive testing recommendations for each ride and results;
☑	☐	7. The amusement ride manufacturer's inspection guidelines for each ride;
☑	☐	8. Operator training records for each operator trained on each ride;
☐	☑	9. Report of itinerary for the current year;
☐	☑	10. Written certification that the ride meets the applicable ASTM international F24 committee standards;
☐	☑	11. Signage must be posted at the point of admission or ticket sale and at least two other locations in close proximity to the amusement ride explaining a patron's duty to report injuries;
☑	☐	12. Proof of insurance policy in effect at the time of operation of the amusement ride with certain coverage in place required by K.S.A. 40-4802 and;
☑	☐	13. All safety instructions for the ride must be posted in plain view on or near the ride in a location where they can be easily read.

Supplemental Compliance Review form (K-ISH 516-A) will detail any violation/violations marked **NO, for each ride**.

Note: All amusement ride records shall be grouped according to ride and shall be maintained by the owner for three years and kept at the location of the ride's operation.

This form reflects the observations at the time of review in accordance with the Kansas Amusement Ride Act. This is a compliance review, and does not certify the safety or integrity of the amusement ride itself, nor provide affirmation that the owner or operator is in full compliance with Kansas statutes and regulations.

Auditor signature: Date: 8-16-2017

On-site contact signature: Date: 8.16.17

KANSAS DEPARTMENT OF LABOR
www.dol.ks.gov

AMUSEMENT RIDE COMPLIANCE REVIEW - SUPPLEMENTAL

K-ISH 516-A (Rev. 7-17)

☑ Temporary Ride ☐ Permanent Ride ☐ Non-profit/Municipality

Inspection date: 8-16-2017 Name of KDOL auditor: Kyle Lang

Ride owner: Kelley's Cowboy Bar the Ride location: Coffeyville, KS

Number of rides: 2

Contact person: Johnna Kelley Phone: 918-915-0044 Email: Johnnakelley@yahoo.com

COMMENTS:

Mag destructive testing was not required for ~~the~~ per Manufactures requirements.

26644 S. 436 Road
~~Vinita~~
Vinita, OK 74301